



**AXIS AND GUIDE INSPECT. (Torque Test)**

X AXIS	YES		Good condition
Y AXIS	YES		Good condition
Z AXIS	YES		Good condition
THETA AXIS	YES		Good condition
VX AXIS	YES		Good condition
YX AXIS	YES		Good condition
STROKE AXIS	YES		Good condition

**PARTS INSPECTION**

Clamps	YES		Good condition
Camera	YES		Working, no cover camera
Y-snugger tooling	YES		Good condition
Squeegee head	YES		Good condition
Conveyor Riel	YES		Good condition
Conveyor Belts	YES		Good
Oxidize parts	YES		It does not have oxide anywhere
Dors Front and Rear (open, close)	YES		Good condition
Paint	YES		General, regular conditions
Sensors	YES		Complete, Good
Panel Control	YES		Complete, Good
Monitors	YES		Complete, Good

**COMMENTS:**

this equipment is in production, without problems

minor scratches to the paint

L